

Technical Bulletin



Your professional partner

N°: TECB-08-12-15_RO

Date :09/12/2015

Diamond model considered :FSM-2V6E/N

Serial number from : 201401xxxxx

to : 201510xxxxx

Production period : January 2014

to : December 2015

Problem :Differential of temperature too important.

Technical solution suggested :Thermostat replacement.


Action (what-when) :The differential you find during testing could be normal during cooking, it is depend on the loading of food. The power of fryer should compensate this phenomena. But to reduce that we decide to change the actual thermostat with another one from EGO.

Defective spare parts codes : No

New replacing spare parts codes : No part code change to avoid any confusion



Actual model : A06056



New model: A06056