

Technical Bulletin



Date : October 13th, 2013

Model : Slicer Mod. 350/GL

We'd like to inform that in the year 2012 a batch of this model has been produced with a new type of lubricating oil in the blade shaft. The idea was improving the belts transmission even after the machine could have been not in use for a long time.

We're referring to the slicers model 350 GL with the serial numbers from 12A03395 to 12A10369.

It now happens that in some units of the abovementioned models some drops of the new grease can fall on the blade pulley and in this case the result is the belt slipping with the consequent loss of power of the motor.

Cleaning the belt and the pulley could be a good solution, but not a permanent in case too much grease had fallen on the pulley.

So in order to solve the problem at 100% we recommend to change both the blade pulley and the belt.

We confirm that for all the machines produced from the end of 2012 until now a different type of grease has been used and this problem did not occur any more.